



GARY R. HERBERT
Governor

GREGORY S. BELL
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining
JOHN R. BAZA
Division Director

Minerals Inspection Report

Report Date: 05/12/2016

Reviewed

[Signature]

Mine Name: Nielson Sandstone	Permit Number: M/023/0012	Mine Status: Active
Operator Name: Ash Grove Cement Company	Inspection Date: 04/28/2016	Permit Fees: Paid
Inspector(s): Wayne Western	Inspection Time: 8:45- 9:15 am	Bond Amount: \$1,403,000
Attendee(s): Josh Nelson, Gordon Jerrett	Weather: sunny and mild	Bond Escalation: 06/08/2019
Inspection Purpose:		Prior Inspection: 04/07/2015

Conclusions and Recommendations

The site is in good standing. The Operator is shipping in slag from the old Geneva steel plant and stockpiling it on site. The stockpiled material should not be confused with mining operations. The product mined is sandstone for silica. No pictures - camera was not working.

Elements of Inspection	Evaluated & Commented	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input type="checkbox"/>
The bond, permit fees and annual reports are current. Mine was active last year.		
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input type="checkbox"/>
There are no underground openings at the site. The highwalls are 15 feet tall and there is no evidence that the public access the area.		
3. Protection of Drainages/Erosion Control	<input checked="" type="checkbox"/>	<input type="checkbox"/>
There are no erosion issues at the site.		
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>
6. Reclamation	<input checked="" type="checkbox"/>	<input type="checkbox"/>
No reclamation was done in 2015.		
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts)	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>
10. Other	<input type="checkbox"/>	<input type="checkbox"/>

Inspector's Signature:

[Signature]

CC:

File: /nrwogmfs1/OGM/GROUPS/MINERALS/WP/M023-Juab/M0230012-NielsonSSQuarry/Inspections/Insp-04282016.pdf

